PROJECT DESCRIPTION

This project involves the modification to the existing traffic control signal at the intersection of MD 140 (Reisterstown Road) and Valley Centre Entrance in Baltimore County, Maryland.

MD 140 is considered to run in a north/south direction.

II. INTERSECTION OPERATION

I. GENERAL

EQUIPMENT LIST

A. Approved S.H.A. equipment to be purchased by the Developer and installed by the Contractor. All equipment in this list shall have catalog cuts submitted for approval

buot to in	staliation.	Specification	
Quantity	Units	Specification Section	Description
1	EA	816	14 ft. steelpedestalpole with break away transformer base.
1	EA	814	12 in., one-way, five section (R,Y,YA,G,GA) adjustable black faced traffic signalhead with pole mounting hardware and tunnelvisors.
1	EA	814	12 in., two-way, two section (symbolic DW, WK) adjustable pedestrian signal head with post top mounting hardware and cut-away visors.
1	EA	817	Pedestrian pushbutton assembly with pushbutton sign.

B. Equipment to be furnished and/or installed by the Contractor. All equipment in this list shall have catalog cuts submitted for approval prior to installation.

0 11		Specification	
Quantity	Units	Section	Description
Lump Sum	LS	108	Mobilization.
Lump Sum	LS	104	Maintenance of traffic.
1	CY	205	Test pit excavation.
4	EA	811	Handhole.
950	LF	810	2-conductor (aluminum shielded) electrical cable (No. 14 A.W.G.).
140	LF	810	2-conductor electrical cable (No. 14 A.W.G.).
150	LF	810	5-conductor electrical cable (No. 14 A.W.G.).
160	LF	810	7-conductor electrical cable (No. 14 A.W.G.).
140	LF	804	Bare copper stranded ground wire (No. 6 A.W.G.).
10	LF	805	2 in. polyvinyl chloride [Schedule 80] electrical conduit - trenched.
285	LF	805	3 in. polyvinyl chloride [Schedule 80] electrical conduit - trenched.
150	LF	805	3 in. polyvinyl chloride [Schedule 80] electrical conduit - slotted in roadway.
0.7	CY	801	Concrete foundation for traffic signal equipment.
1	EA	804	Ground rod -¾in. diameter x 10 ft. length.
15	LF	556	24 in. wide HAPPTPM white for stop line.
Lump Sum	LS		Relocate existing Interconnect Cable (Approx. 550 LF).
Lump Sum	LS		As-built for S.H.A. [on CADD].

CONTACT LIST

The contact persons for District *4 are as follows:

Mr. Randall Scott Assistant District Engineer - Traffic 410-321-2781

Mr. Joe McMahon Assistant District Engineer - Utility 410-321-2841


Mr. Dave Ramsey Assistant District Engineer - Maintenance 410-321-2761

Mr. Richard L. Daff Chief, Traffic Operations Division 410-787-7630




(dG-)	1 (A) Y Y (GG) G	2 (R) (Y) (G)	3 R Y G QY	4 (R) (Y) (G)	5 (R) (Y) (G)	6	7 ® Y 6	8.9 P	10,
-------	------------------------	------------------------	------------------------	------------------------	------------------------	---	------------	----------	-----

Phase 1 & 6	G G	G	G G−	R	R	R	R	DW	DW	4
1 Change	G ← Y	G	G ← Y—	R	R	R	R	DW	DW	₹
Phase 2 & 6	G	G	G	G	G	R	R	wĸ	DW	<
Ped Clearance	G	G	G	G	G	R	R	FL/DW	DW	⊳
2 & 6 Change	Y	Y	Υ	Y	Υ	R	R	DW	DW	00
Phase 4	R	R	R	R	R	G	G	DW	DW	Р
4 Change	Ŕ	R	R	R	R	Υ	Υ	DW	DW	
Phase Alt 4	R	R	R	R	R	G	G	DW	WK	P
Ped Clearance	Ř	R	R	R	R	G	G	D₩	FL/DW]
Alt 4 Change	R	R	R	R	R	Υ	Y	DW	DW	
Flashing Operation	FL/Y	FL/Y	FL/Y	FL/Y	FL/Y	FL/R	FL/R	DARK	DARK	→ → → →







TRAFFIC ENGINEERING DESIGN DIVI (General Information Plan)

TS NO. 2103-B GI

T.I.M.S. NO. E-779

MD 140 (Reisterstown Road) at Valley Centre

DRAWN BY: F. Brownley	F.A.P. NO.	N/A
CHECKED BY:	S.H.A. NO.	BW996M82
SCALE: N/A	COUNTY:	Baltimore
DATE: <u>January 7, 2002</u>	LOG MILE:	XXX

The intersection operation is to remain unchanged.

The existing pedestalpole, conduit and interconnect in the NW quadrant of the intersection are to be relocated.